



L1 7.2 mH

R12 909 OHM
 R13 110 OHM
 R14 110 OHM
 R15 10K OHM

C1 1 μ F
 C2 1 μ F
 C3 22 μ F

CONNECTOR PTO6A-11-32P

DRAWN FROM 860F-4 RADIO ALTIMETER
 TEST FIXTURE, SCHEMATIC DIAGRAM,
 FIGURE 905 IN COLLINS 860F-4 COMPONENT
 MAINTENANCE MANUAL

THIS ASSY. BOX USED WITH THE LRA-6101
 HARNESS WILL ALLOW USER TO TEST THE
 860F-4 WITH THE COLLINS TEST
 PROCEDURES. REQUIRES NOTE SHEET TO
 CROSS REFERENCE LINAIRE SWITCHES AND
 TIP JACKS TO COLLINS TEST FIXTURE

Model 860F P9 TEST ASSY
 Name LRA5152_ASSY_TESTER

LiaAire Engineering Inc.
 50913 Ford RD
 Garden City, MI 48135
 www.liaaire.com

Drawn
 By: L.J.L. REV

Date: